

#### MISSOURI DEPARTMENT OF HEALTH STATE PUBLIC HEALTH LABORATORY DATAMASTER MAINTENANCE REPORT

RECEIVED	OHSS Breeth Alcohol Program
By Carol Day	at 8:15 am, Mar 04, 2010

<b>大學的學</b>		The state and th
Complete this report in duplicate at the time of the regular is repaired. Send copy to Department of Health; retain original	monthly preventive maintenance	check, and whenever instrume
DATAMASTEP SM	aspartment me.	DATE OF INSPECTION
204100	•	03-02-2010
LOCATION OF INSTRUMENT (STREET AND CITY) CHARITON COUNTY OF INSTRUMENT (STREET AND CITY) CHARITON COUNTY OF INSTRUMENT (STREET AND CITY) CHARITON COUNTY	ITY SHERIFF'S DEPARTMEN KEYTESVILLE, MO	TIME OF INSPECTION
CHECKLIST: Place a check (✓) to the left of each item if four in observed values where determined.) Unchecked items must	ind to be satisfactory or if operating	within established limits. (Wri
DIAGNOSTIC CHECK (PRINTOUT ATTACHED)		, .
COMPUTER	DETECTOR	
PROGRAM	☑ FILTERS	
☐ HEATERS SAMPLE CHAMBER50_ °C	QUARTZ STANDARD	P
FLOW DETECTOR	☐ CALIBRATION	
PUMP HIGH SPEED	FRINTER	٠.
INDICATOR LIGHTS	-	
TIME AND DATE	· · · · · · · · · · · · · · · · · · ·	
SIMULATOR TEMPERATURE (34 °C ± 0.2°C) 34°C		
CALIBRATION CHECK -		
Run three tests using a standard solution. All three test spread of .005 or less. Check the box corresponding to the RECIRCULATION PUMP)	s must be within $\pm$ 5% of the stane ne standard solution being used. (I	ndard value and must have a PRINTOUT ATTACHED) (USE
O.100% STANDARD - MUST READ BETWEEN 0.095% a O.040% STANDARD - MUST READ BETWEEN 0.038% a ONLY ONE STANDARD IS TO BE USED PER MAINTENA	nd 0.042% INCLUSIVE	
EST 1095 TEST 2	095 TEST 3	.095
PERFORM R.F.I. TEST (PRINTOUT ATTACHED)		
NUMBER OF REFUSALS, SINCE LAST MAINTENANCE REI FOLLOWS: (DO NOT INCLUDE SIMULATOR TESTS)	PORT, AND NUMBER OF BREATH	TESTS IN EACH RANGE AS
FUSALS Ø (004) 2 (.0509)	(.1014) (.1519)	Ø (Over .19)
st any new parts and describe any alteration or modification d within established limits (use other side if necessary)  MEETS DEPARTMENT OF HEALTH		ument to operate satisfactorily
REPCO MARKETING, INC LOT	# 09002	
•	08-31-11	
SPECTING OFFICER	Table 11 - 12 - 12 - 12 - 12 - 12 - 12 - 12	
NATHER // /	PRINT NAME	
Kant Kento	REID T FESSLE	R
E II PERMIT NUMBER/EXPIRATION DATE 20032 02-05-2012	TELEPHONE NUMBER (060 - 385 - 2132	
2011014 04-04-6014	エレゼレー・ハヘフェノレン	

### CERTIFICATE OF ANALYSIS

MANUFACTURER AND SUPPLIER: RepCo Marketing, Inc. LOT NUMBER: 09002 EXPIRATION DATE: August 31, 2011 at 11:59 p.m.

RepCo Marketing, Inc. certifies the following:

RepCo Marketing, Inc. manufactured, tested and supplied Lot Number <u>09002</u> of Alcohol Certified Solution for simulators. Random samples of said lot number were analyzed by an independent laboratory utilizing a gas chromatograph and found to contain <u>.1206</u> gms/dl +/-.003 gms/dl wt/vol ethanol (95% Confidence).

The alcohol and distilled water used in the solution were found to be free of any interfering substance.

This solution will produce a vapor alcohol value of <u>.100</u> +/-3% gms/210L Breath when heated to 34 Degrees Celsius +/-0.2 Degrees Celsius in a simulator (95% Confidence).

The date of manufacture for this lot number is September 1, 2009.

The expiration date for this lot number is August 31, 2011 at 11:59 p.m.

This document is a true representation of the original Certificate of Analysis.

Cecil B. Garner, President RepCo Marking, Inc.

### State of Missouri DEPARTMENT OF HEALTH



### PERMIT TYPE II



### REID T FESSLER

is hereby authorized to instruct and supervise operators, train instructors, inspect, calibrate, perform field repairs, and operate the following breath analyzer(s):

calibrate, perform field repairs, an	a oberate are lonowing product analyzer (2).
	DATAMASTER
for the determination of the alcoho air. Issued under the provisions of	ollc content of blood from a sample of expired (alveolar) sections 577.020 through 577.041. RSMo 1986.
02/05/2010	Interim Director
200032	Director of State Public Health Laboratory  Manyant T. Brandly
Expires 02/05/2012	Director, Department of Health
MO 580-0771 (7-88)	Lab. 4 (R7-98)

Face This Side Down - This Edge In First

## **BAC DataMaster**Evidence Ticket

MISSOURI STATE HIGHWAY PATROL DAG DATAMASTER SERIAL NUMBER 204100 03/02/10

ARREST TIME: 08:06
SUBJECT NAME:
TEST
DOB: 11/11/11 SEX: M
STATE/D.L.: MO/TEST
ARRESTING OFFICER:
FESSLER/R/T
OFFICER I.D.: 998
TESTING OFFICER:
FESSLER/R/T
OFFICER I.D.: 998
PERMIT NUMBER: 200098
EXPIRATION DATE: 02/05/18
MISCELLAMEOUS DATA:

--- BREATH AMALYSIS ---

RADIO INTERFERENCE

Face This Side Down - This Edge In First

### **BAC DataMaster**Evidence Ticket

MISSOURI STATE KIGHWAY PATROL BAC DATAMASTER SERIAL NUMBER 204100 -03/02/10

TESTING OFFICER:
FESSLER/P/T
OFFICER I.D.: 992
PERMIT NUMBER: 200932
EXPIRATION DATE: 02/05/12
MISCELLANEOUS DATA:
...10 TEST

#### --- SUPERVISOR MODE ---

BLANK TEST	. 890	17:48
INTERNAL STANDARD	VERIFIED	17:48
EXTERNAL STANDARD	, 395	17:48
BLAWK TEST	. 909	17:49
EXTERMAL STAMPARD	.995	17:49
ELAPK TEST	a SIIII	17:56
EXTERMAL STAYDARD	.895	17:50
BLANK TEST	raint is promised them are an all differences of the first production of the first production of the	17:51

N = 0 | GIM. = .1 | AVG. = .895

Operator Signature

Operator Signature

2208-02

### Face This Side Down - This Edge In First

# **BAC DataMaster**Evidence Ticket

MISSOURI STATE HIGHWAY PATROL BAC DATAMASTER SERIAL NUMBER 204100 03/02/10 17:43

--- DIAGNOSTIC CHECK ---

COMPUTER:

UKAY

PROGRAM (84-87-2009):

OKAY

HEATERS

SAMPLE CHAMBER:

Sec

FLOW DETECTOR:

OKAY

PUMP

HIGH SPEED:

OKAY

DETECTOR:

OKAY

FILTERSE

OKAY

QUARTZ STANDARD:

OKRY

CALIBRATIONS

UKAY

#### PRINTER TEST

!"#\$%&'()\*+,-./0123456789:;<=>?@ABCDEFG
HIJKLMNOPORSTUVWXYZ[\]^\_\abcdefghijklmno
pqrstuvwxyz{|}>\*

Operator Signature

2208-02